

Product Obsolescence Notification

EK-015846-SL-A-BULGIN PRODUCT OBSOLESCENCE_(PAXXXX)

Issue Date : 16 February 2018

Dear valued customer,

Whilst we continue to invest in our Bulgin & Arcoelectric brands through development of new products, following a strategic review of our product portfolio, effective immediately, there will be a removal of all biocote options from our switch range to ensure ongoing competitiveness of our remaining portfolio in our ever-changing market.

The following products will be made obsolete within the following timescales:

- 1. Formal customer notification beginning 16th February 2018**
- 2. Final customer order date by 16th March 2018**
- 3. Final ship date to customer by 16th June 2018**

| | | | | |
|-------------------|--------------------|--------------|--------------------|-------------------|
| A1072SAAAAB | C1353ARBR2-602AW-B | C1560ABBB-B | C6057ALNAJB | H8550VBBB-551W-B |
| A1074SAAAAB | C1353ARBR2-B | C1560ALAAAB | C6058ALBA2-B | H8550VBBB-B |
| B045BC01 | C1353ARNAAB | C1560XAAABB | C6058ALBG2-B | H8553VBBA2-B |
| B045BC02 | C1353ARNAEB | C1560XABBR-B | C6058ALNADB | H8553VBBA3-551W-B |
| B045BC03 | C1353ARNALB | C1561ALAAAB | C6058ALNAEB | H8553VBBG2-B |
| C1300AAAAAB | C1353ARNANB | C1570AAAAAB | C6058ALNAFB | H8553VBBG3-551W-B |
| C1300AAAAADB | C1500AAAAAB | C1570AAAADB | C6059ALBA2-B | H8553VBBG3-B |
| C1300AABB-602AW-B | C1500AABB-B | C1570AABB-B | C6059ALNAFB | H8553VBBR2-551W-B |
| C1300AABB-B | C1500ALAABB | C1570AABR-B | C6060ALAABB | H8553VBRR2-B |
| C1300ABAAAAB | C1500ARAAAAB | C1570ALAAAB | C6060ALBB-1197W-B | H8553VBNACB |
| C1300ABAABB | C1500ARBB-B | C1570ALBB-B | C6061ALAAAB | H8553VBNAEB |
| C1300ABBB-602AW-B | C1500WAAAAB | C1570ARAABB | C6061ALBB-B | H8553VBNAJB |
| C1300ABBB-B | C1500WRAACB | C1570ARBB-B | C6067ALBR2-B | H8553VBNALB |
| C1300ALAAAB | C1500WRBB-B | C1570WAAABB | C6067ALNABB | H8553VBNBAB |
| C1300ALAABB | C1501AAAAAB | C1570WABB-B | C6090ALBR2-1197W-B | H8553VBNCRB |
| C1300ALBB-602AW-B | C1501AAAABB | C1572AAAAAB | C6090ALNAKB | H8553VBNCXB |
| C1300ALBB-B | C1501AABB-B | C1572AABB-B | F0167LOAAAB | H8553VBNKKB |
| C1300ARAABB | C1501AABR-B | C1572ALAAAB | F0180LOAAAB | L167-B |

| | | | | |
|--------------------|-------------|--------------------|-------------------|-------------|
| C1300ARAADB | C1501ABAABB | C6050ALAAAB | F1025MOAAAB | L180-B |
| C1300ARBB-602AW-B | C1501ABBB-B | C6050ALAACB | F1026MOAAAB | M1025PBL54 |
| C1300ARBB-B | C1501ALAAAB | C6050ALAAEB | F1095MOAAAB | M1026PCL17 |
| C1350AAAAAB | C1501ARAAAB | C6050ALBB-1196W-B | F1096MOAAAB | M1165ABLR20 |
| C1350AAAAAB | C1501ARBB-B | C6050ALBB-1197W-B | H8300ABAAAAB | S6050ALGAAB |
| C1350AABB-602AW-B | C1501WAAAAB | C6050ALBB-B | H8300ABBB-B | SA1072/B |
| C1350AABB-B | C1501WABB-B | C6051ALAAAB | H8301ABAAAAB | SA1072-B |
| C1350ABAABB | C1510AAAAAB | C6051ALBB-B | H8301ABBB-B | SA1074-B |
| C1350ABAADB | C1510AAAADB | C6053ALBA3-1196W-B | H8350ABAAAAB | |
| C1350ABBB-602AW-B | C1510AABB-B | C6053ALBA3-1197W-B | H8350ABAADB | |
| C1350ABBB-B | C1510AABR-B | C6053ALBG2-1197W-B | H8350ABBB-B | |
| C1350ALAABB | C1510ALAAAB | C6053ALBG3-1197W-B | H8350ABBR-B | |
| C1350ALAAFB | C1510ALBB-B | C6053ALBR2-1197W-B | H8351ABAAAAB | |
| C1350ALBB-602AW-B | C1510WAAAAB | C6053ALBR2-B | H8351ABBB-B | |
| C1350ALBB-B | C1510WABB-B | C6053ALBR3-1197W-B | H8353ABNAAB | |
| C1350ARAAAB | C1520AAAAAB | C6053ALNAEB | H8353ABNABB | |
| C1350ARAACB | C1520AABB-B | C6053ALNAGB | H8500VBAAAAB | |
| C1350ARBB-602AW-B | C1520ABAABB | C6053ALNALB | H8500VBAAFB | |
| C1350ARBB-B | C1520ABBB-B | C6053ALNAMB | H8500VBBB-551W-B | |
| C1353AABG2-602AW-B | C1520ALAAEB | C6053ALNATB | H8500VBBB-B | |
| C1353AABG2-B | C1520ARAAAB | C6053ALNAUB | H8500XBAAEB | |
| C1353AABR2-602AW-B | C1520ARBB-B | C6053ALNBNB | H8500XBBBR-A-B | |
| C1353AABR2-B | C1520WAAAAB | C6054ALBG2-B | H8503VBBA3-551W-B | |
| C1353AANADB | C1520WABB-B | C6054ALNAEB | H8503VBBG2-551W-B | |
| C1353AANAJB | C1522ALAAAB | C6055ALBA2-B | H8503VBBG7-B | |

| | | | | |
|--------------------|--------------|--------------|--------------|--|
| C1353AANAMB | C1550WAAAAB | C6055ALNABB | H8503VBRR2-B | |
| C1353AANAUB | C1550WABB-B | C6056ALBR2-B | H8503VBFAAB | |
| C1353AHNABB | C1553PLNAAB | C6056ALNACB | H8503VBNAEB | |
| C1353ALGNBB | C1553PLNACB | C6057ALBA2-B | H8503VBNATB | |
| C1353ALGNCB | C1560AAAAAB | C6057ALBG2-B | H8503VBNBIB | |
| C1353ARBG2-602AW-B | C1560AABB-B | C6057ALBR2-B | H8550VBAAAB | |
| C1353ARBG2-B | C1560ABAAAAB | C6057ALNAIB | H8550VBACAB | |

If you have any questions about this obsolescence, please do not hesitate to contact your local sales representative or authorised distributors.

Notes:

Please note that Elektron Technology plc reserves the right to limit lifetime buy quantities based on capacity and material availability.

Customer service and technical support for these products are available up to 1 year post the date listed above.