

Product Obsolescence Notification



MK-009078-SL

Issue Date : 18 September 2015

Dear Valued Customer,

Whilst we continue to invest in our Bulgin & Arcoelectric brands through development of new products, following a strategic review of our product portfolio, effective immediately, there will be a consolidation of the fuseholder range to ensure ongoing competitiveness of our remaining portfolio in our ever-changing market.

The following products will be made obsolete within the following timescales:

- 1. Formal customer notification beginning 18th September 2015**
- 2. Final customer order date by 18th December 2015**
- 3. Final ship date to customer by 18th March 2016**

| Arcoelectric Part No | Bulgin Part No |
|-----------------------------|-----------------------|
| A003300AAA | FX0417 |
| A003300AAB | FX0418/1 |
| A003500AAB | FX0418/2 |
| B0333RAAAA | FX0460 |
| B0340RAAAA | FC535953 |
| B0340RAAAB | QX3777 |
| B0340RDAAA | QX3778 |
| B0340RDAAD | |
| B0340RDAAF | |
| B0341RAAAB | |
| B0341RDAAA | |
| F0520MOAAA | |
| F0520MOAAB | |
| F0873MOAAA | |
| F0873MOAAC | |
| M279-BLACK | |
| M520 | |

| | |
|------------|--|
| T0332RAAAA | |
| T0332RDAAC | |
| T0333RAAAA | |
| T0333RAAAC | |
| T0340RA | |
| T0340RAAAB | |
| T0340RAAAC | |
| T0340RAAAD | |
| T0340RDAAD | |
| T0340RDAAF | |
| T0341RAAAB | |
| T0341RDAAA | |
| T0341RDAAB | |

Replacement Part Options

Where possible, replacement parts options are available as detailed below. Specifications may vary slightly from the original part, so please review.

| Obsolete Part No | Replacement Part No |
|------------------|---------------------|
| FX0417 | D0347RAAAB |
| FX0418/1 | D0345RAAAE |
| FX0418/2 | D0345RAAAE |
| A003300AAA | FX0380/BK |
| A003300AAB | FX0380/BK |
| A003500AAB | FX0180/BK |
| A0789SAAAA | 12298 |
| B0333RAAAA | FX0454/S |
| B0340RAAAA | FX0458/1 |
| B0340RAAAB | FX0458/1 |

| | |
|------------|------------------------|
| B0340RDAAA | FX0458/1 |
| B0340RDAAD | FX0458/1 |
| B0340RDAAF | FX0458/1 |
| B0341RAAAB | FX0454 |
| B0341RDAAA | FX0455 |
| M520 | 11327 or 9820 or 12932 |
| M873 | 11327 or 9820 or 12932 |
| T0332RAAAA | FX0365 |
| T0332RDAAC | FX0365 |
| T0333RAAAA | FX0454/S |
| T0333RAAAC | FX0454/S |
| T0340RA | FX0458/1 |
| T0340RAAAB | FX0458/1 |
| T0340RAAAC | FX0458/1 |
| T0340RAAAD | FX0458/1 |
| T0340RDAAD | FX0458/1 |
| T0340RDAAF | FX0458/1 |
| T0341RAAAB | FX0454 |
| T0341RDAAA | FX0455 |
| T0341RDAAB | FX0455 |

If you have any questions about this obsolescence, please do not hesitate to contact your local sales representative or authorised distributors.

Notes:

Please note that Elektron Technology plc reserves the right to limit lifetime buy quantities based on capacity and material availability.

Customer service and technical support for these products are available up to 1 year post the date listed above.