

MK-009921-SL Issue Date : 01 April 2016

Dear Valued Customer,

Due to our ongoing product improvement initiatives, it is now proposed to up issue FX0419 in line with this. These changes include the addition of a second spring in the cap assembly. Up issuing the current part number and not creating a new part number means that this will also eliminate the requirement for our customers to update their approval files and associated costs.

Affects part numbers: FX0419

If you have any questions about this change, please do not hesitate to contact your local sales representative or authorised distributors.