

Product Obsolescence Notification



MK-009921-SL

Issue Date : 12 February 2018

Dear Valued Customer,

Due to our ongoing product improvement initiatives, we are progressing with renewed VDE approval activities on our fuse holder range. This involves superseding the certificate types seen below with the more recent versions.

| Present information on VDE current cert |
|--|
| DIN EN60127-1 (VDE 0820-1):2011-12; EN60127-1:2006+A1:2011 |
| DIN EN60127-6 (VDE 0820 Teil 6):2003-10; EN 60127-6:1994+A1:1996+A2:2003 |
| IEC 60127-1(ed.2);am1 |
| IEC 60127-6(ed.1);am1;am2 |

| VDE Pending (estimation AUG 2018) |
|--|
| DIN EN60127-1 (VDE 0820-1):2015-12; EN60127-1:2006+A1:2011+A2:2015 |
| DIN EN60127-6 (VDE 0820-6):2015-07; EN60127-6:2014 |
| IEC 60127-1:2006 |
| IEC 60127-1:2006/AMD1:2011 |
| IEC 60127-1:2006/AMD2:2015 |
| IEC 60127-6:2014 |

| Fuse holder parts already approved to the latest standard include: |
|---|
| FX0430/48 |
| FX0430/63 |

| Approvals pending for August 2018: | | |
|---|----------|----------|
| FX0357 | FX0369/2 | FX0455/S |
| FX0359 | FX0419 | FX0456 |
| FX0367/1 | FX0454 | FX0457 |
| FX0367/2 | FX0454/S | FX0462 |
| FX0369/1 | FX0455 | FX0463 |



If you have any questions about this change, please do not hesitate to contact your local sales representative or authorised distributors.