

Product MOQ Adjustment



PRODUCT MOQ ADJUSTMENT

Issue Date : 02 August 2018

Dear valued customer,

Whilst we continue to monitor our manufacturing processes, we need to adjust a number of part MOQ's to align with efficient batch manufacturing practices. These changes include both decrease and increases in MOQ's, effective immediately, there will be an adjustment to the following part number MOQ's.

Sales Part No	Current Sales MOQ	Proposed Sales MOQ
14064	25	100
MP0045/1D1AM012	50	40
MPZ016/F	25	30
MPZ019/F	25	30
MPZ022/F	25	30
MPZI019/F/BL/24	25	30
MPZI022/F/GN/24	25	30
MPZI022/F/RD/24	25	30
MPZI022/F/D1/24	25	30
MPZI022/F/BL/24/L	25	30
MPZ016/G/RD/AL	25	30
MPZ016/G/GN/AL	25	30
MPZI022/F/BL/24	25	30
PX0578/63	100	200
PX0592/15/63	100	200
PX0716/48	50	100
PX0717/2/15/ST	50	100
PX0717/4/15/ST	50	100
PX0717/5/15/ST	50	100
PX0717/6/15/ST	50	100
PX0718/1/15/ST	50	100
PX0718/2/15/ST	50	100

PX0718/3/15/ST	50	100
PX0718/4/15/ST	50	100
R13112BLAG	500	1000
R13112BNBB	800	1000
R13112CAAA	500	1000
R13112DAAA	500	1000
R13112LPLA	500	1000
R13112LPL02	500	1000
R13208FAAA	500	1000
R13244AAAA	500	1000
R13244AAAE	3000	1000
R13244AAAB	500	1000
R13244AAAD	500	1000
R13244BNAA	500	1000
R13244BNAB	500	1000
R13066AAAA	500	1000
R171000AAA	500	1000
R09092BNAA	500	1000
C3900BAAAA	250	500
C3900BEAAA	1000	500
C3900BEAAC	7000	1000
C3901BAAAA	500	1000
C3910BAAAA	250	500
C3910BEAAA	500	1000
C3911BAAAA	250	1000
C3920BAAAA	250	500
C3921BAAAA	500	1000
C3921BEAAA	500	1000
C3922BAAAA	250	500
C3922BEAAA	500	1000

C3950BAAAA	500	1000
C3950BBAAA	250	1000
C3950BFAAB	500	1000
C3950BFAAC	50000	10000
C3961BBAAA	250	1000
C3970BAAAA	1000	250
C3972BBAAA	250	1000
T3900BAAAD	500	1000
PX0714/2/15/28	50	100
PX0714/4/15/28	50	100
PX0714/3/15/28	50	100
14232/1	500	1
14191	50	1000
14192	50	1000
14193	25	1000
14194	25	1000
PX0416/1M00	25	50
PX0416/3M00	25	50
PX0416/5M00	25	50
PX0441/2M00	10	150
PX0441/3M00	10	100
PX0441/4M50	10	50
PX0442/2M00	10	150
PX0443	25	50
PX0446	25	50
PX0456	25	50
PX0457	25	50
PX0837/2M00	10	100
PX0837/3M00	10	60
PX0837/5M00	10	40

PX0838/2M00	10	80
PX0840/A/2M00	10	100
PX0840/A/5M00	10	50
PX0840/B/2M00	10	100
PX0840/B/3M00	10	100
PX0840/B/5M00	10	50
PXMBNI16FIM12ASCPG9	100	25
PXMBNI16FBF12ASCPG9	100	25
PXMBNI16RPM12ASCM16	100	25
PXMBNI16RPF12ASCM16	100	25
PXMBNI23FBM12ASCPG9	25	30
PXMBNI23FBM19ASCPG9	25	30
PXMBNI23FBF12ASCPG9	100	30
PXMBNI23FBF19ASCPG9	100	30
PXMBNI23RAF12ASCPG9	100	30
PXMBNI23RAF19ASCPG9	100	30
PXMBNI23FPM12ASCM20	100	30
PXMBNI23FPM19ASCM20	100	30
PXMBNI16FBF03ASCPG9	100	25
PXMBNI16FBF04ASCPG9	100	25
PXMBNI16FBF05ASCPG9	100	25
PXMBNI16FBF06ASCPG9	100	25
PXMBNI16FBF08ASCPG9	100	25
PXMBNI16FIM03ASCPG9	100	25
PXMBNI16FIM04ASCPG9	100	25
PXMBNI16FIM05ASCPG9	100	25
PXMBNI16FIM06ASCPG9	100	25
PXMBNI16RPF03ASCM16	100	25
PXMBNI16RPF04ASCM16	100	25
PXMBNI16RPF05ASCM16	100	25

PXMBNI16RPF06ASCM16	100	25
PXMBNI16RPF08ASCM16	100	25
PXMBNI16RPM03ASCM16	100	25
PXMBNI16RPM04ASCM16	100	25
PXMBNI16RPM05ASCM16	100	25
PXMBNI16RPM06ASCM16	100	25
PXMBNI16RPM08ASCM16	100	25
PXMBNI23FIM12ASCPG9	100	30
PXMBNI23FIM19ASCPG9	100	30
PXMBNI23FIM12ASC	25	30
PXMBNI23FIM19ASC	25	30
PXMBNI23FBF12ASC	25	30
PXMBNI23FBF19ASC	25	30
PXMBNI23RAF12ASC	25	30
PXMBNI23RAF19ASC	25	30
PXMBNI23FPM12ASC	25	30
PXMBNI23FPM19ASC	25	30

If you have any questions about this notification, please do not hesitate to contact your local sales representative or authorised distributors.